




BSP V1.0.535

Release Notes





BSP V1.0.535 Release Notes

Current BSP released available on website: <https://www.exorint.com/en/panel-bsp>

Build numbers references:

V1.0.344 Previous release version number

V1.0.532 Current release version number

V1.0.535 Only for UN65 due to BSP-1744 *

All items are classified as:

Feature implementation of a new feature

Bug solution to problems reported by users. Summary may include the Case ID number assigned during technical support.

Platform details:

UN60 eSMART04, eSMART04M, eSMART07M, eSMART10

UN61 PLCM07

UN64 eTOP607L, eTOP610L

UN65 eX707, eX710, eX715, eX721, eX707G, eX710G, eX707FB, eX715FB, eXware707, eXware707Q

UN70 eX705, eXware703

UN71 JSmart705, JSmart707, JSmart710, JSmart715, JSmart721

UN72 eXware705

UN73 eSMART107



Ticket ID	Summary	Type	UN60	UN61	UN64	UN65	UN70	UN71	UN73	Notes
BSP-910	Firewall support	Feature	•	•	•	•	•	•	•	
BSP-438	NAT/Forward service support	Feature	•	•	•	•	•	•	•	
BSP-1289	Support for USB Wi-Fi dongles: Edimax AC600 and D-Link N300	Feature	•	•	•	•	•	•	•	
BSP-1559	Zero dimming enhancement	Feature	•			•				eX707G, eX710 only
BSP-1696	NFC Support	Feature						•		
BSP-1744 *	Update PWM frequency backlight for 21.5" displays	Feature				•				eX721, JSmart721 only
BSP-1578	Enable NTP local time reference clock	Feature	•			•	•			
BSP-1691	Connection to Access Point from mobile devices not working with wifi dongles - Case ID: 201905964	Bug	•	•	•	•	•	•	•	
BSP-1575	Improved event behavior when touchscreen is disabled - Case ID: 201903357	Bug				•	•		•	
BSP-1554	Cursor may not appear at boot with some mouse devices - Case ID: 201900506	Bug	•	•	•	•	•	•	•	
BSP-1611	800Kbit CAN baudrate support - Case ID: 201903886	Bug			•	•	•		•	
BSP-1574	Improved Ethernet messages in case of high network traffic - Case ID: 201901784	Bug	•			•	•			
BSP-1615	Software bridge not working via API - Case ID: 201904105	Bug				•	•		•	
BSP-911	Integrate lower impact retry mechanism in Cloud Service - Case ID: 201903548	Bug	•	•	•		•			
BSP-1105	Improved timing of ssh service boot up - Case ID: 201905815	Bug	•							
BSP-1554	Cursor may not appear at boot with some mouse devices - Case ID: 201900506	Bug	•			•	•			
BSP-1384	Screen remains black after toggling external timeout variable - Case ID: 201808435	Bug				•				